

Republic of the Philippines PROVINCE OF ZAMBOANGA DEL SUR Municipality of San Pablo OFFICE OF THE SANGGUNIANG BAYAN



EXCERPT FROM THE MINUTES OF THE 7^{TH} REGULAR SESSION OF THE 12^{TH} SANGGUNIANG BAYAN MEMBERS OF SAN PABLO, ZAMBOANGA DEL SUR, HELD AT THE MULTI-PURPOSE BUILDING, ON AUGUST 18, 2025.

RESOLUTION NO. 2025-17

"A RESOLUTION ALLOWING THE OFFICE OF THE MUNICIPAL MAYOR, LGU SAN PABLO, ZAMBOANGA DEL SUR TO DEMOLISH THE FOLLOWING STRUCTURES WITHIN THE MUNICIPAL PREMISES, NAMELY: KITCHEN BUILDING LOCATED AT THE BACK SIDE OF THE LIGA BUILDING, AND THE TWO (2) UNITS BODEGA AT THE 3RD FLOOR BESIDE COMMISSION ON AUDIT (COA) OFFICE AND BESIDE BIDS AND AWARDS COMMITTEE (BAC) OFFICE."

WHEREAS, the municipality of San Pablo, Zamboanga del Sur is committed to ensuring the safety of its constituents, employees, and visitors within the municipal compound;

WHEREAS, certain structures located within the municipal premises have been found to be in a state of disrepair, posing risks to public safety and hindering the efficient maintenance and repair of the municipal building;

WHEREAS, the Municipal Engineer has conducted an inspection and issued a certificate of demolition attesting to the necessity of removing said structures due to their dilapidated condition and compromised structural integrity, viz;

1. Kitchen Building

Location: Backside of Liga Building, near ECCDC

Size/Dimension: $9.50 \text{ m} \times 4.00 \text{ m}$ and $6.00 \text{ m} \times 5.00 \text{ m}$

Reason for demolition: Structural integrity issues - dilapidated

condition.

Reference: Certificate of Demolition no. 08-25-001 issued by the

Municipal Engineer

2. Stock Room/Bodega

Location: 3rd Floor, Ring Wing, beside COA Office

Size/Dimension: 2.50 m x 3.00 m

Reason for demolition: Structural integrity issues - Repair/maintenance

of Municipal Building.

Reference: Certificate of Demolition no. 08-25-002 issued by the

Municipal Engineer

3. Stock Room/Bodega

Location: 3rd Floor, Ring Wing, beside BAC Office

Size/Dimension: 3.00 m x 4.00 m

Reason for demolition: Structural integrity issues – Repair/maintenance

of Municipal Building.

Reference: Certificate of Demolition no. 08-25-003 issued by the

Municipal Engineer

WHEREFORE, on motion by Hon. Ronald M. Taganos, severally seconded, be it

RESOLVED, as it is hereby resolved, ALLOWING THE OFFICE OF THE MUNICIPAL MAYOR, LGU SAN PABLO, ZAMBOANGA DEL SUR TO DEMOLISH THE FOLLOWING STRUCTURES WITHIN THE MUNICIPAL PREMISES, NAMELY: KITCHEN BUILDING LOCATED AT THE BACK SIDE OF THE LIGA BUILDING AND THE TWO (2) UNITS BODEGA AT THE 3RD FLOOR BESIDE COMMISSION ON AUDIT (COA) OFFICE AND BESIDE BIDS AND AWARDS COMMITTEE (BAC) OFFICE.

Let copies of this resolution be furnished to the different offices concerned for information and reference.

"UNANIMOUSLY ADOPTED".

Certified correct:

TA P. SUMBI Sangurian Secretary

Verified:

DENNIS P. CORDERO

Floor Leader

Attested:

ATTY. FLAVIO . CORDERO, JR. Vice Mayor/Presiding Officer

